


QBTA: ON [ALT-F1/BB=60]

File Dynamics, Inc.

DPF



ACCEPT SQ-OFF FL-OFF PR-OFF  contact File Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	VMX= 3.3 FMX= 51 AMX= 100 EMX= 0.2 MEX= 100 FVP= 1.00 ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: 13522 CALIBRATION FACTOR: 1031 6/V PAK (X5000) DATE: 1 Feb 05 PDA OPERATOR: <i>[Signature]</i>
	OP: DAVE Iver: 4.057 AT: PIEZOELECTRIC

<-AT:PIEZORESISTIVE

OP: DAVE Iver: 4.057

AT:PIEZOELECTRIC->