

DPF

Pile Dynamics 19-Jan-07 13:41 LE 39.6 ft AR 1.7 in ² EM 30000 Ksi SP 0.492 K/ft ³ WS 16810 ft/s WC 16862 ft/s JC 0.40 FM 1.00 UM 1.00 EA/C 30.3 Ks/ft UN KIPS×0.1 FR 20000 MB 30 DL -40 UT -1 PK 1 TM-PEAK F1 500 F2 213 A1 999 A2 1060	FS — BN 335 PJ: sn 10 SL 2615/ 3440/ 99 PN: HOPBAR TG F2 -- US A2 F2 3.3			
TS 12 B PD: 20361-060 LP 0.00 ft TB 8.0 T1 9.6 2L/C 4.7 VA 1000 VE 1022 LI 1.0				
<table style="width: 100%; border: none;"> <tr> <td style="width: 30%;">ACCEPT SQ-OFF FL-OFF PR-OFF</td> <td style="text-align: right; padding-right: 20px;"> VMX= 4.9 FMX= 75 AMX= 179 EMX= 0.4 MEX= 147 FVP= 0.99 </td> </tr> </table>			ACCEPT SQ-OFF FL-OFF PR-OFF	VMX= 4.9 FMX= 75 AMX= 179 EMX= 0.4 MEX= 147 FVP= 0.99
ACCEPT SQ-OFF FL-OFF PR-OFF	VMX= 4.9 FMX= 75 AMX= 179 EMX= 0.4 MEX= 147 FVP= 0.99			
<table style="width: 100%; border: none;"> <tr> <td style="width: 30%; vertical-align: top;"> contact Pile Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916 </td> <td style="vertical-align: top;"> ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: <u>20361</u> CALIBRATION FACTOR: <u>1060 G/V</u> PAK (#5000): _____ DATE: <u>19-JAN-07</u> PDA OPERATOR: <u>[Signature]</u> </td> </tr> </table>			contact Pile Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: <u>20361</u> CALIBRATION FACTOR: <u>1060 G/V</u> PAK (#5000): _____ DATE: <u>19-JAN-07</u> PDA OPERATOR: <u>[Signature]</u>
contact Pile Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: <u>20361</u> CALIBRATION FACTOR: <u>1060 G/V</u> PAK (#5000): _____ DATE: <u>19-JAN-07</u> PDA OPERATOR: <u>[Signature]</u>			
<-AT:PIEZORESISTIVE OP: alex [ver:4.05] AT:PIEZO-ELECTRIC->				