




ACCEPT SQ-OFF FL-OFF PR-OFF



contact Pile Dynamics USA  
 with your questions  
 tel USA - 216 - 831- 6131  
 fax USA - 216 - 831- 0916

&lt;-AT:PIEZORESISTIVE

VMX= 4.1 FMX= 63 AMX= 139  
 EMX= 0.3 MEX= 123 FUP= 1.00

ACCELEROMETER CALIBRATION

N.I.S.T. Traceable

SERIAL NUMBER: 10094

CALIBRATION FACTOR: 1150 G/v

PAK-(\*5880)- DATE: 21-OCT-13

PDA OPERATOR: *[Signature]*

OP: ALEX [ver:4.05]

AT:PIEZOELECTRIC-&gt;