


QBTA: ON [ALT-F1/BB=60]

File Dynamics, Inc.

DPF



<input type="checkbox"/> ACCEPT	<input type="checkbox"/> SQ-OFF	<input type="checkbox"/> FL-OFF	<input type="checkbox"/> PR-OFF
		UM _X = 4.6 FM _X = 72 AM _X = 139 EM _X = 0.3 ME _X = 141 FVP= 1.00	
ACCELEROMETER CALIBRATION N.I.S.T. Traceable			
SERIAL NUMBER: <u>10374</u>			
CALIBRATION FACTOR: <u>1020%</u>			
PAK (*5000): _____		DATE: <u>28 APR 16</u>	
PDA OPERATOR: <u>[Signature]</u>			
<-AT:PIEZORESISTIVE		OP: laine [ver:4.05]	
AT:PIEZOELECTRIC->			

contact File Dynamics USA
with your questions
tel USA - 216 - 831- 6131
fax USA - 216 - 831- 0916